

FIRMWARE NOTE

CHANGE METHOD FOR STATUS SIGNAL DETECTION FOR INTERNAL STATUS DEVICES

Manufacturer:	meteocontrol GmbH
Address:	Spicherer Straße 48 86157 Augsburg, Germany
Product:	blue'Log X-Series (XM/XC)
Firmware	11.2.2

From firmware version 11.2.2 the method of the signal detection has changed as followed:

- Digital signal changes for internal status devices will now be detected by a resistance measurement.
- In previous firmware versions the digital signal changes have been detected by a current measurement.
- This change has no negative effect on the quality of the signal detection.
- The changes are firmware-internal and no further/manual actions (reconfiguration) have to be taken to make this change effective.
- This change in the signal detection has been implemented to optimize (reduce) the inside temperature of connected MX I/O-modules.
- Recommendation is to update all blue'Log XM and blue'Log XC devices